



**XXIVth World
Road Congress
Mexico 2011**
Mexico City 2011.

The Great East Japan Earthquake Disaster

Keiichi Tamura

- Public Works Research Institute, Japan
- Research Coordinator for Earthquake Engineering
- ke-tamura@pwri.go.jp




Contents

- Overview of earthquake
- Overview of damage
- Damage of road bridges
- Damage of earth structures and slopes
- Summary




World mega earthquakes

(Earthquake Research Institute, University of Tokyo)



Where a M9.0 earthquake occurred



Overview of earthquake

Origin time	2:46 pm, March 11, 2011 (JST)
Epicenter	Off the Pacific coast of Tohoku
Magnitude	9.0
Focal depth	24km
Seismic intensity	7 (Kurihara, Miyagi Prefecture) 6+ (28 Cities and towns in Miyagi, Fukushima, Ibaraki and Tochigi Prefectures)
Aftershocks (M \geq 7.0)*	3:08 pm, March 11, M=7.4
	3:15 pm, March 11, M=7.7
	3:25 pm, March 11, M=7.5
	11:32 pm, April 7, M=7.1 (Seismic intensity 6+)
	5:16 pm, April 11, M=7.0 (Seismic intensity 6-)
	9:57 am, July 10, M=7.3 (Seismic intensity 4)

* From March 11 to September 15, 2011


Damage statistics (Fire Defense Agency)

Casualty	15,960
Injured	6,110
Missing	4,004
Destroyed houses	115,222
Partially destroyed houses	162,457
Partially damaged houses	579,476
Fires	287

* As of September 9, 2011








Typical strong motion records



Source: National Research Institute for Earth Science and Disaster Prevention

Acceleration response spectra



Source: National
Research Institute for
Earth Science and
Disaster Prevention

Classification of damage to highway bridges

Effects of tsunami



Effects of ground motion



Effects of soil liquefaction



Bridges damaged by tsunami

- About 80 bridges collapsed due to tsunami.
- Backfill soils were washed out.



Shi-Kitakami Ohashi Bridge



Kesen-Ohashi Bridge



Nijyuichihama Bridge



Bridges damaged by ground motion

- One bridge collapsed due to ground motion on national highways.
- Old or not-retrofitted bridges suffered damage at RC piers, bearings, etc.



Collapse of bridge with pile-bent columns



Damage to RC pier with small amount of reinforcement



Damage to pier top



Damage to movable bearing




Bridges damaged by soil liquefaction

- Subsidence of backfill soil of abutment, shortening of deck-end gap resulting from movement of substructure, etc. occurred.



Koizumi Ohashi Bridge damaged by tsunami

- 6-span steel girder bridge (two 3-span-continuous girders).
- All girders and one RC pier were washed away.



After earthquake (March 15)



About 6 years ago




Steel girder washed away



P3 Pier

Ezaki Ohashi Bridge damaged by ground motion

- 9-span PC box girder bridge designed by pre-1980 specifications
- Shear cracks, spalling off of cover concrete and buckling of longitudinal rebars at section of cut-off of longitudinal rebars



Damage to RC columns at section of cut-off of longitudinal rebars

Temporary repair by wrapping up with carbon fiber sheet

Sendai-Tohbu Viaduct damaged by ground motion

- 4-span steel box girder and 2-span steel girder bridge
- Designed by post-Kobe Earthquake specifications
- Elastomeric rubber bearings were ruptured.



Sendai-Tohbu Viaduct



Ruptured rubber bearings

Damage of earth structures and slopes

- Damage to road embankments was similar to those observed in the past earthquakes.
- Road slopes collapsed and blocked roads.
- Tsunami affected road embankments, retaining walls and slope protection works.




Subsidence of road embankment and temporary repair (Joban expressway)



Collapse of embankment adjacent to national highway

- Collapse volume was 11,000m³.
- The embankment was developed by filling up a valley for residential area about 40 years ago.




Upper part and toe of collapse

- Collapsed soils covered the entire width (4 lanes) of a national highway.



Slope failure of national highway



- Collapsed by the main shock on March 11, and collapsed again 3 days later.
- Slope consists of Triassic slate.
- Red broken line : collapsed area by the earthquake
Red dotted line : scarp in the upper slope



Impacts of tsunami on earth structures and retaining walls

- Washed away embankment and stripping of the shotcrete on the cut slope.
- Undamaged concrete block retaining walls.



Summary

- A magnitude 9.0 earthquake was the largest earthquake ever recorded in Japan and the fourth largest in the world since 1900.
- Tsunami was more influential than ground shaking in both human and physical damage.
- Bridges designed by new design specifications and seismically retrofitted performed well. While those designed by old specifications or not-retrofitted suffered damage at RC piers, bearings, etc.
- Damage to road embankments and slopes was similar to those observed in the past earthquakes.

